

Instapak® Quick RT®

Foam Packaging

Sealed Air®



Protect

Anything and
Everything,
Anywhere



Unique Pack

Uniquepack Paketleme Malzemeleri ve
Sistemleri Ticaret Limited Şirketi
Ferahevler Mah. Fıstık Çamı Sok. Dış Kapı No:1 A Daire:1
Sarıyer / İSTANBUL T: 0216 807 27 70

www.uniquepack.com.tr

Sealed Air Authorized Distributor in Turkey



ENJOY ALL THE PROVEN BENEFITS OF INSTAPAK®
FOAM PACKAGING

- Easy-to-Use:** Anyone can become a packaging expert – instantly.
- No Start Up Costs:** No dispensing system or warming
No dispensing system or warming
- Versatile:** Protects products of almost any size, shape
and weight.
- Fast:** Expands in seconds to form custom-fit protective
foam cushions.
- Convenient:** Takes up little space and is completely
mobile so you can use it anywhere.
- Customer Satisfaction:** Product arrives in a neat
professional package.

NO EQUIPMENT NEEDED

Instapak® Quick RT® Foam Packaging is a protective packaging solution you can take and use anywhere. By expanding up to 27 times their original size, Instapak® Quick RT® foam bags save valuable space, making them the ideal on-demand packaging solution. For best results, activate bags stored between 18°C to 32°C.



Bag Number	#25	#45	#65
Bags Per Standart Box	30	30	24
Bag Size	46x41	46x51	56x51

Bag Number	#10	#20	#40	#60*	#80	#100
Bags Per Standart Box	36	36	30	30	24	24
Bags Per Bulk Box	180	128	112	104	72	72
Bag Size	38x46	46x46	46x61	46x61	54x68	64x69

*Bag No. 40 has the same footprint as Bag No. 60, but has 25% less foam volume.

**Bag No. 100 has 25% more foam volume than Bag No. 80.

CREATE PROTECTIVE FOAM CUSHIONS IN THREE SIMPLE STEPS


Instapak Quick® RT protective foam packaging can be activated right out of the box and requires no additional equipment. See user's guide for complete instructions and helpful hints.



PRESS!

Press hard on the
component "A"
oval to break the seal

1



PAT!

Alternately "pat"
back and forth
on the "A" and "B"
ovals (fteen to twenty
times).

2



PACK!

Nestle the product
into the rising foam.
Repeat the process
as needed.

3